

FIG. 1

10




FIG. 2




FIG. 3




FIG. 4

include claim 1 - 11
discussion, emphasize IC
layout symmetry

73




FIG. 5
LNA 72

inductors are the layout problem
because of their size





FIG. 6
PA 84